



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 600R • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

April 26, 1984

W3P84-1156
Q-3-A29.13

Director of Nuclear Reactor Regulation
Attention: Mr. G.W. Knighton, Chief
Licensing Branch No. 3
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUBJECT: Waterford 3 SES
Docket No. 50-382
Licensee Qualification

Dear Sir:

Conversations with Mr. R. Benedict of the Licensee Qualification Branch have identified additional questions on our revised FSAR Section 13.1 docketed with FSAR Amendment 34 (1/84). The attached provides the information necessary to respond to all of Mr. Benedict's questions with one exception. The exception is submittal of more detailed resumes for Nuclear Operations personnel; these resumes will be submitted within about one week.

Yours very truly,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RMF/pco

cc: E.L. Blake, W.M. Stevenson, J.T. Collins, D.M. Crutchfield,
J. Wilson, G.L. Constable, R. Benedict

M&P

ATTACHMENT 1

1. Attached Tables 1-3 provide additional information on authorized staffing levels.
2. Attached Figures 1 and 2 detail the composition of the Operations Group and the normal shift complement. Those in the position of Auxiliary Reactor Operator (AO)-Training spend their time working on qualification for Reactor Operators when not assisting the AOs. Staff positions in the Operations group assist the Operations Superintendent in the administrative duties of the group. The ROs and AOs on the shift complement who are not part of the minimum shift composition normally fill out the fire brigade.
3. Plant procedures require that at all times that the Plant Manager is unavailable, a Duty Plant Manager be designated who can take on all the responsibilities and authority of the Plant Manager. The Duty Plant Manager position may be filled by either the Assistant Plant Manager-Technical Services, the Assistant Plant Manager-Operations & Maintenance or the Operations Superintendent. Personnel in operations and management who will hold a Waterford 3 SRO at fuel load are the Operations Superintendent and Assistant Plant Manager-Operations & Maintenance.
4. Revised resumes will be provided under separate cover.

TABLE 1

Nuclear Support & Licensing Staffing

Nuclear Support & Licensing Manager	(1)
Technical Advisor	(1)
Clerical	(2)
Licensing Manager	(1)
Safety/Environmental	(4)
Regulatory Compliance	(3)
Onsite Licensing	(2)
Nuclear Support Manager	(1)
Radiation & Control	(4)
Nuclear Engineer & Fuel Management	(4)
Chemistry/Radiochemistry	(2)

TABLE 2

Engineering & Nuclear Safety Department Staffing

Engineering & Nuclear Safety Manager	(1)
Clerical	(2)
Mechanical Engineering	(7)
Electrical Engineering	(6)
I&C Engineering	(7)
Civil Engineering	(2)
Nuclear Safety Supervisor	(1)
Technical Review	(3)
Independent Safety Engineering	(5)
Operations Assessment	(6)
	<u>40</u>

TABLE 3

Technical Services Unit Staffing

Technical Support Superintendent	(1)
Clerical	(4)
Chemistry	(15)
System Engineering	(8)
Support Engineering	(7)
Performance and Analysis	(10)

45

Radiation Protection Superintendent	(1)
Radwaste	(20)
Health Physics	(28)

49