

R

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14604

KEITH W. AMISH
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

December 21, 1970

Dr. Peter A. Morris, Director
Division of Reactor Licensing
U. S. Atomic Energy Commission
7920 Norfolk Avenue
Bethesda, Maryland 20014



Subject: Report on Failure of Anchor Bolts in
Primary System Component Supports
Ginna Station - Docket 50-244

Dear Dr. Morris:

During the scheduled shutdown from September 30 to October 15, 1970 a broken stud was found on one of the supports for a primary system component. An investigation was immediately started. The Atomic Energy Commission Division of Compliance and Division of Reactor Licensing were notified and informed that at the conclusion of the investigation a report would be submitted.

To fulfill that commitment, please find attached five (5) copies of Report of Stud Failure-Ginna Station.

/S/LK 2/19/71

2/90
H.D.

Asp. Binder
* ~~Enclosed Report for PDR~~

Very truly yours,

Keith W. Amish
Vice President
Electric and Steam

Attachments (5)

8304150540 701221
PDR ADOCK 05000244
S PDR

10870

I