



Telegram

444P EST JAN 31 72 PB227 MC122 SSC540

M RHA176 ML PDF 3 EXTRA ROCHESTER NY 31 300P EST

DAMES P O'REILLY DKR REGION 1 DIV COMPLIANCE US AEC 970 BROAD
ST NEWARK NJER 970 BROAD ST

THIS IS TO CONFIRM MY CONVERSATION AT 1404 THIS DATE WITH LEE
SPESSARD OF YOUR OFFICE IN REGARDS TO AN OBNORMAL OCCURENCE
AT GINNA STATION AT 1010 ON JAN 31 1972 WHILE CONDUCTIONS
PT5.2 7UNDervOLTAGE AT UNDERFREQUENCY PROTECTION OF TEST OF
4160 COLT BUSES A ESTINGHOUSE TYPE KF UNDERFREQUENCY RELAY
FAILED OPERATE PROPERLY. A PROPERLY CALIBRATED SPARE RELAY
WAS INSTLLED AND 5TH PT5.2 TEST WAS THAN SUCCESSFUL COMPLETED
CHARLES E PLATT SUPERINTENDENT GINNE STATION ROCHESTER GAS
AND ELECTRIC CORP

104 1010 31 1972 PT5.2 4160 KF PT5.2

(314).

8004200039 720201
PDR ADOCK 05000244
Q PDR

87-1201 (RS-69)

Copy sent PDR