



Telegram

VEA253(1645)(1-026152C009)PD 01709773 1643 No-ACK-NO-ADDRESSER SC
ICS IPMVEID MVN AGENT SECTION 1/10 941A No-312-858-2660 3:57
ZCZC 04206 TDVE MORRIS ILL 91 01-09 155P CST To be mailed or filed
PMS MR BOYCE GRIER WUX To be delivered (indicate DA or BV)
DIRECTOR DIVISION OF COMPLIANCE REGION 3 US ATOMIC ENERGY COMMISSION
799 ROOSEVELT RD
GLEN ELLYN ILL

SUBJECT DPR19 DRESDEN NUCLEAR POWER STATION UNIT 2

THIS WILL CONFIRM THE CONVERSATION WITH MR FISHBAUCHER OF YOUR
OFFICE OF 1130 HOURS THIS DATE CONCERNING HPCI STEAMLINE BREAK
DETECTION SENSOR DRIFT.

DURING ROUTINE SURVEILLANCE FOUND OUT OF CALIBRATION SENSORS
WHICH ISOLATE HPCI STEAMLINE ON HIGH FLOW. TECH. SPEC. TABLE 3.2.1
REQUIRED A SETTING OF LESS THAN OR EQUAL TO 150 INCHES OF WATER
FOR DIPS 2-2352 AND 2353. THESE WERE FOUND AT 154.6 AND 151
RESPECTIVELY. BOTH WERE LEFT AT 146 INCHES WATER.

Call AM

W P WORDEN SUPERINTENDENT COMMONWEALTH EDISON DRESDEN NUCLEAR
POWER STATION RTE 1 MORRIS ILL

JAN 1 1973

50237
inquiry

8304210088 730214
PDR ADDCK 05000237
S PDR