



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

December 23, 1975

Director of Nuclear Reactor Regulation  
Attn: Mr. Karl Goller  
Assistant Director for Operating Reactors  
Division of Reactor Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973, concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers both inside and outside of containment was completed on December 10, 1975.

All snubbers were considered operable at this inspection. Fluid was added to the reservoir of the "A" Steam Generator Anker-Holth restraints. The source of leakage could not be determined. The present leakage rate is not sufficient for maintenance prior to the refueling shut-down. Upon adding fluid to one Bergen-Paterson unit, leakage was observed at the accumulator, indicating a possible scored cylinder in the area of the desired fluid level. The unit will be monitored more frequently until plant conditions facilitate the replacement of the accumulator.

Very truly yours,

*L. D. White, Jr.*

L. D. White, Jr.

50-244

14281

8304210232 751223  
PDR ADDCK 05000244  
PDR  
3

(COPY SENT REGION I)