


**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 27, 1984

W3K84-0980  
Q-3-A35.07.103

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: LP&L Letter W3K84-0631 dated March 16, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 103  
"Radflex Wall Penetrations"  
Second Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on April 30, 1984.

At the present time, approximately 9 penetrations (RB3) remain to be inspected/repared in the Fuel Handling Building, this is scheduled to be completed in early May 1984.

The Final Report will be submitted to the USNRC on May 15, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8405080038 840427  
PDR ADOCK 05000382  
S PDR

IL 27/10

Mr. John T. Collins

April 27, 1984  
W3K84-0980

Page 2

cc: Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814