

MGMATLT HSB

3-036090E135 05/15/74

ICS IPMBNGZ CSP

2057298316 MGM TDBN ATHENS AL 100 05-15 0455P EDT

ZIP 30303



western union

Mailgram



US ATOMIC ENERGY COMMISSION  
REGION 2 DIRECTORATE OF REGULATORY OPERATIONS 230 PEACHTREE ST  
NORTHWEST  
ATLANTA GA 30303

BFAO-7432T UNIT 2 TURBINE BUILDING EXHAUST FANS OPERATED APPROXIMATELY  
16 DAYS WITHOUT CONTINUOUS AIR MONITORING. ON MAY 14 1974  
THE UNIT 2 TURBINE BUILDING EXHAUST VENT CONTINUOUS AIR MONITORS  
2-RM-90-249 AND 251 WERE FOUND INOPERABLE A VENDER ASSEMBLY  
ERROR CAUSED THE AIR SAMPLE TO BYPASS ALL RADIATION DETECTORS  
SUCH THAT THE SAMPLE WAS NOT MONITORED UNIT 1 REACTOR WAS IN  
THE COLD SHUT DOWN CONDITION AND UNIT 2 WAS IN PREPARATION FOR  
INITIAL FUEL LOADING  
H J GREEN BROWNS FERRY NUCLEAR PLANT

16:56 EDT

MGMATLT HSB

8305040787 740524  
PDR ADDCK 05000259  
S PDR