




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 27, 1984

W3K84-0978
Q-3-A35.07.60



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-0632 dated March 16, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 60
"Turnover Documentation and Inadequate Hanger Weld Problems T&B"
Eighth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on April 27, 1984.

At the present time, documentation reviews and field verification is scheduled to be completed in mid May 1984. The Final Report will be submitted on May 25, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8405080172 840427
PDR ADOCK 05000382
S PDR

IE-27,16

Mr. John T. Collins

April 27, 1984

W3K84-0978

Page 2

cc: Mr. E. L. Blake

Shaw, Pittman, Potts & Trowbridge

1800 M Street, N.W.

Washington, D.C. 20036

Mr. W. M. Stevenson

Monroe & Lemann

1424 Whitney Building

New Orleans, Louisiana 70130

Mr. W. A. Cross

7910 Woodmont Avenue

Suite 1200

Bethesda, Maryland 20814