



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET

P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 27, 1984

W3K84-0979

Q-3-A35.07.102



Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

REFERENCE: LP&L Letter W3K84-0816 dated April 5, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 102
"Failure to Install Dowels and Shear Blocks"
Third Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on April 27, 1984.

At the present time, the corrective action has been completed and verification of the supporting documentation is scheduled to be completed on May 7, 1984.

The Final Report will be submitted to the USNRC on May 11, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8405080184 840427
PDR ADOCK 05000382
S PDR

IE-27.10

Mr. John T. Collins

April 27, 1984

W3K84-0979

Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814