

MGMATLT HSB

2-035031E126 05/06/74

ICS IPMBNGZ CSP

2057298316 MGM TDBN ATHENS AL 100 05-06 0436P EDT

ZIP 30303



western union

Mailgram



US ATOMIC ENERGY COMMISSION REGION 2
DIRECTORATE OF REGULATORY OPERATIONS 230 PEACH TREE ST NORTHWEST
ATLANTA GA 30303

SURJECT BFA0-7425T AT 843 AM MAY 5 1974 THE HPCI SYSTEM FAILED
TO DELIVER WATER TO THE REACTOR WHEN INITIATED ON LOW WATER
LEVEL FOLLOWING REACTOR SCRAM OVERSPEED TRIP WAS APPARENT CAUSE
IT WAS IMMEDIATELY RESTARTED MANUALLY AND PERFORMED SATISFACTORILY
DURING THE MANUAL SHUTDOWN CYCLE THE INVERTER POWER SUPPLY FUSE
BLEW. IT WAS REPLACED AND THE HPCI DECLARED OPERABLE AT 1230
PM ON THE SAME DATE. INVESTIGATION OF BOTH FAILURES IS CONTINUING
H J GREEN BROWNS FERRY NUCLEAR PLANT

16:36 EDT

MGMATLT HSB

8305050433 740515
PDR ADDCK 05000259
S PDR

Handwritten:
HJG
50259