

MGMWSHT HSB

Z-035438E291 10/18/74

ICS IPMBNGZ CSP

6159422920 MGM TDBN MORRIS IL 100 10-18 0455P EDT
ZIP



western union

Mailgram



J F O'LEARY, DIRECTOR, DIRECTORATE OF LICENSING
U.S. ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545



SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM
A CONVERSATION WITH F MAURA OF YOUR OFFICE AT 1520 HOUR THIS DATE
CONCERNING A FAILURE OF 2B RECIRC PUMP SUCTION VALVE TO SHUT WHEN
2B RECIRC PUMP WAS ISOLATED DUE TO RECIRC PUMP SEAL FAILURE DISCHARGE
VALVE DID SHUT ASSURING LPCI INJECTION CAPABILITY SUCTION VALVE
WAS SHUT BY SPECIAL PROCEDURE THIS AFTERNOON UNIT IS SHUTTING DOWN
TONIGHT TO REPAIR VALVE AND PUMP SEAL FAILURE OF VALVE OCCURRED
ABOUT 0300 THIS MORNING

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH
EDISON CO RURAL ROUTE 1 MORRIS IL 60450

16155 EDT

MGMWSHT HSB

8305190197 741025
PDR ADDOCK 05000237
S PDR

50-237
incident

10904 III

COPY SENT REGION