

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

May 11, 1984

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Re: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

Section 9.3.2.2 of the Catawba Safety Evaluation Report discusses License Condition 17, Post Accident Sampling System. My letter of February 7, 1984 provided additional information in response to this license condition. Included was a copy of procedure AP/O/A/5500/31, Estimate of Failed Fuel Based on I-131 Concentration. This procedure has been revised to include consideration of isotopes other than I-131. A copy of the revised procedure is attached.

Very truly yours,



Hal B. Tucker

ROS/php

Attachment

cc: Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

NRC Resident Inspector
Catawba Nuclear Station

Mr. Robert Guild, Esq.
Attorney-at-Law
P. O. Box 12097
Charleston, South Carolina 29412

Palmetto Alliance
2135 1/2 Devine Street
Columbia, South Carolina 29205

Mr. Jesse L. Riley
Carolina Environmental Study Group
854 Henley Place
Charlotte, North Carolina 28207

8405140235 840511
PDR ADOCK 05000413
E PDR

Boo1
11