

OF PROBLEMS. AND MOST OF THEM HAVE BEEN IDENTIFIED UNTIL
THE PROBLEM IS RESOLVED. IT IS ON APRIL 1 1974 FOLLOWING THE
SHUTDOWN TO START THE UNIT ONE REFUELING OUTAGE MAIN STEAM ISOLATION
VALVES WERE LEAK TESTING WITH THE FOLLOWING RESULTS A STEAM LINE
WITH D.DSCPH A STEAM LINE UNABLE TO TEST OBSTRUCTION IN TEST
OF A STEAM LINE AT D.DSCPH A STEAM LINE AT D.DSCPH C AND D STEAM LINES
AND LEAKAGE CAUSING TECHNICAL DIFFICULTY WITH THE UNIT
REPAIRS ARE TO DISASSEMBLE THE AFFECTED VALVE INSPECT AND FOR

THE VALVE SEALS DURING THE OUTAGE.

N J KALIVIRAKIS

WNN

812P 8201 APRIL 1 74

LSAEC HNS GINA

AD WSH



WESTERN UNION INCOMING

2788