

MGMWSHT HSB
2-035902E295 10/10/74
ICS IPMBNGZ CSP
8159422920 MGM TDBN MORRIS IL 100 10-22 0529P EDT
ZIP 20545

western union Mailgram



50-237

J F OLEARY, DIRECTOR, DIRECTORATE OF LICENSING, US ATOMIC ENERGY
COMMISSION
WASHINGTON DC 20545

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM
A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE AT 1600 HOURS THIS
DATE CONCERNING FAILURE OF 2 BERGEN PATERSON PIPE RESTRAINTS IN
UNIT 2 DRYWELL 2 WEEKS OF OPERATION ON THE SYSTEM PRIOR TO FAILURE
SNUBBERS WERE REPLACED PRIOR TO UNIT START UP FAILURE WAS DISCOVERED
21 OCTOBER 1974 SEAL MATERIAL WAS POLYURETHANE

B STEVENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH
EDDISON CO RURAL ROUTE 1 MORRIS IL 60450

17130 EDT

MGMWSHT HSB



10941

8305230202 741022
PDR ADOCK 05000237
S PDR

COPY SENT REGION

III