

FLX INCOMING

50-237

T GVN

USAEC GTWN

ESAECGPWN

USAEC GTWN

WU INFOMASTER 1-051870C228 08/16/74

FLX WU WSH

00097

TVX 7108280476 USAEC GTWN

SPL097 WAA303(2007)(1-043177C228002)PD 08/16/74 1841

ICS IPMVEID MVN

04101 TDVE MORRIS IL 89 08-16 334P CDT

PMS J F O LEARY

DIRECTOR

DIRECTORATE OF LICENSING

WUX US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH F. MAURA OF YOUR OFFICE AT 1450 HOURS THIS DATE CONCERNING DRIFT OF HIGH PRESSURE COLLANT INJECTION SYSTEMS (HPCI) LOW PRESSURE ISLOATION SWITCHES TO RESET POINT ABOVE THE 90 PSI AT WHICH HPCI IS REQUIRED TO BE OPERABLE. CONDITIONS WAS DISCOVERED AT 1750 15 AUG 74 DURING ROUTINE SURVEILLANCE ACTUAL VALUES OF SWITCHES WERE 94 AND 93 PSI IMMEDIATELY RESET TO LESS THAN 85 PSI

BB STEPHENSON SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON CO RR MORRIS IL 60450.

8305230370 740823  
PDR ADDCK 05000237  
S PDR

2351 EDT

USAEC GTWN



COPY SENT REGION 13