



western union

Telegram

1974 JUN 10 10 10 10

VEA248(1601)(1-029896C161)PD 06/10/74 1559

ICS IPMVEIC MVN

03209 IDVE MORRIS ILL 123 06-10 147P CDT

PMS MR JAMES G KEPPLER

REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS (OTHER THAN MONEY ORDERS)

REGION 3 WUX

Is PHYSICAL DELIVERY requested? (YES-AGENT, NO-ADDRESSEE)

US ATOMIC ENERGY COMMISSION

AGENT SECTION

ADDRESSEE SECTION

799 ROOSEVELT ROAD

Date dtd 6-10 1358 To F.m. By 81 -

GLENELLYN ILL 50137

To be mailed or filed

Attempts to deliver (Indicate DA or BY)

by 6-10 405P

mail

Received  
50-237

SUBJECT DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3

THIS WILL CONFIRM A CONVERSATION WITH F MAURA OF

YOUR OFFICE AT 1325 HOURS THIS DATE CONCERNING A FAILURE

OF A THREE QUARTER INCH NIPPLE ON REACTOR FEED PUMP DISPATCH

LINE 3-3201-24 A THROUGH WALL CRACK APPROXIMATELY ONE QUARTER

305240092 740610  
PDR ADDCK 05000249  
PDR

8F-1201



Telegram

INCH IN LENGTH DEVELOPED DURING OPERATION ON THREE QUARTER  
INCH NIPPLE BETWEEN MANUAL DRAIN VALVE 3-3201-500 AND 501  
AND THE COMMON FEED PUMP DISCHARGE HEADER 3-3201-24 INCH  
PREPARATION FOR REPAIR ARE CURRENTLY UNDER WAY ADDITIONAL  
DETAILS AND CORRECTIVE ACTION WILL BE SUPPLIED IN THE FORM OF  
A TEN DAY LETTER IN ACCORDANCE WITH SECTION 6.6.B.1.A OF  
THE TECHNICAL SPECIFICATION

B B STEPHENSON

SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY

? R 1

MORRIS ILLINOIS 60450

JUN 12 1974