



Telegram

1014A EDT JUL 22 72 AB035 AAC020(0751)(1-002538C204003)PD

07/22/72 0749

ICS IPMMZFA MIA


ZCZC 053 A NL PDC TDMZ HOMESTEAD FLO 21

PMS DIRECTOR REGION 2 DRO, US ATOMIC ENERGY COMMISSION, DLR  
230 PFACHTREE ST NORTHWEST ATLA

FLORIDA POWER AND LIGHT COMPANY REPORTS ABNORMAL OCCURRENCES  
72-1 AND 72-2 72-1 DURING A SIMULATED SAFETY INJECTION CONDITION  
FOLLOWED BY A SIMULATED LOSS OF OFFSITE POWER THE 3A 4KV BUS DID  
NOT STRIP PREVENTING THE A DIESEL GENERATOR FROM CLOSING ONTO  
THE BUS. 72-2 DURING A SIMULATED LOSS OF OFFSITE POWER FOLLOWED ONE  
MINUTE LATER BY A SIMULATED SAFETY INJECTION CONDITION  
SIMULTANEOUS STARTING OF 4A INTAKE CW PUMP 3A RESIDUAL HEAT  
REMOVAL PUMP AND 3A AND 4A S1 PUMPS CAUSED LOW VOLTAGE  
CONDITION ON 4A KV BUS WITH SUBSEQUENT STRIPPING OF THAT BUS.

SF-1201 (R5-69)

8306020421 720728  
PDR ADDCK 05000250  
S PDR



Telegram

AAC 02012

SINCE FUEL WAS NOT IN THE REACTOR THERE WAS NO NUCLEAR SAFETY

HAZARD INVOLVED WITH EITHER OF THESE OCCURRENCES WRITTEN REPORT  
WILL BE SUBMITTED AS REQUIRED BY TECHNICAL SPECIFICATIONS  
AD SCHMIDT SUPT GEN STATIONS.

72-1 72-2 72-1 3A 4KV 72-2 4A 3A 3A 4A S1 4A KV.