



# Telegram

VEA242(2049)(2-056667E342)PD

Call 1709 Am

1975 DEC

858-2660

office

ICS IPWENCZ CSP

8159424449 IDBN MORRIS IL 71 12-08 0849P TESTHONOR T2

PMS

JAMES G KEPPLER REGIONAL DIRECTOR

ATTEMPTS TO DELIVER:

DIRECTORATE OF REGULATORY OPERATIONS REGION III, WUX

US NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-25, DRESDEN NUCLEAR POWER STATION, UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH MR P JOHNSON OF YOUR OFFICE AT 1530 HOURS THIS DATE CONCERNING FAILURE OF BERGAN-PATERSON PIPING RESTRAINT ON THE UNIT 3 CLEAN-UP SYSTEM 8 INCH SUPPLY LINE INSIDE THE DRYWELL DUE TO THE LOSS OF HYDRAULIC FLUID. THE FLUID LOSS WAS ATTRIBUTED TO A FAULTY ZIRC FITTING WHICH WAS IMMEDIATELY REPLACED. ALL OTHER RESTRAINTS WERE FOUND OPERABLE.

B B STEPHENSON, SUPERINTENDENT

DRESDEN NUCLEAR POWER STATION, COMMONWEALTH EDISON COMPANY CO

RR 1 MORRIS IL 60450

NNNN

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

Incident Notification From: Commonwealth Edison Company 50-249  
(Licensee & Docket No. (or License No.))

Transmittal Date : December 11, 1975 Dresden Station #3

Distribution:

IE Chief, FOSB  
IE Chief, FC&EB  
IE:HQ(4)  
Licensing(4)  
DR Central Files  
IE Files

Distribution:

IE Chief, FSOB  
IE Chief, FC&EB  
IE:HQ(4)  
L:D/D for Fuels & Materials  
DR Central Files  
IE Files

