

Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Telecopied Date 6-27-75
of 1 11:45 a.m.
DC
By GR

cc:
Bernard C. Rusche, Director
Directorate of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

50-249

SUBJECT: DPR- 25, Dresden Nuclear Power Station, Unit 3.

This will confirm a conversation with Mr. P. Johnson of
your office at 0800 hrs this date concerning LOCATION OF SURFACE
CRACK INDICATIONS ON THE COLLET HOUSING PORTION OF
CONTROL ROD DRIVE HOUSING OUTER TUBE DURING OVERHAUL
OPERATIONS. FOUR CONTROL ROD DRIVES HAVE BEEN FOUND
TO CONTAIN THESE DEFECTS. THE INDICATIONS PRESENTED
NO OPERATIONAL PROBLEMS, HOWEVER COMPLETE FAILURE
OF THIS PORTION OF THE HOUSING COULD HAVE BEEN
DETRIMENTAL TO OPERATION OF THE DRIVE MECHANISM.
THE CONTROL ROD DRIVE MANUFACTURER IS BEING CONTACTED
TO DETERMINE THE EXTENT OF THESE POSSIBLE OPERATIONAL
PROBLEMS. FURTHER INFORMATION WILL FOLLOW IN A 10 DAY
REPORT.

B306090123 750904
PDR ADOCK 05000249
P PDR

COPY SENT TO: PDR ☒
IPDR ☒
NSIC ☐
TIC ☐

To Call:
GE - 5-858-2660x16 (auto) - on 6
DC - 9-1-301-492-7617 (auto)
WU - 815-942-4449/4321

Station Dist: Originator (copy)
Incident File (copy)
Telegram File (original)

B. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
E.R. #1
Morris, IL 60450 6-27-75 12 noon
Telephone: 815-942-2920/2921x212
(teletype x262)