



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-76-230

Telecopy: Region III, Attention: Mr. C. Felerabend

June 17, 1976

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 1
Docket No. 50-254, DPR-29
Appendix A, Sections 6.6.B.1.e, 3.5.C.1

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of a Reportable Occurrence as required by Technical Specification 6.6.B.1 within 24 hours of the occurrence.

On June 17, 1976, the Unit 1 High Pressure Coolant Injection system motor speed changer failed to come off the Low Speed Stop during its monthly surveillance. Investigation found the motor speed changer linkage to be bound. After freeing the linkage, the motor speed changer operated satisfactorily. Proper operation of the Low Speed Stop limit switch is under investigation.

This occurrence was discussed by telephone with Mr. Knop of your office on June 17, 1976. Further information will be provided by Reportable Occurrence Report No. RO 50-254/76-19 which will be submitted within 14 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
Station Superintendent

NJK/IK

cc: G. A. Abrell

*Rec'd 9:30 AM -
6/18/76 - J.A.*

8306130021 760617
PDR ADCK 05000254
S PDR

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Incident Notification From: Commonwealth Edison Company 50-254
(Licensee & Docket No. (or License No.))

Transmittal Date: June 28, 1976 Quad-Cities Station-Unit #1

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
Licensing(4)
DR Central Files
IE Files

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
L:D/D for Fuels & Materials
DR Central Files
IE Files