



Telegram

VEE050(1005)(2-010694E153)PD 06/02/75 1005

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 73 06-02 1005A EST

PMS JAMES G KEPPLER, REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS REGION 3, WUX

US NUCLEAR REGULATORY COMMISSION

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-25, DRESDEN NUCLEAR POWER STATION, UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH MR P JOHNSON OF YOUR OFFICE AT 1445 HOURS 5-30-75 CONCERNING EXCESSIVE LEAKAGE THROUGH PRIMARY CONTAINMENT FEED WATER ISOLATION CHECK VALVES 3-220-58B AND 3-220-62B DURING REFUELING OUTAGE SURVEILLANCE. LEAKAGE IS BELIEVED AT THIS TIME TO BE CAUSED BY FAILURE OF THE VALVE DISC SEAL. BOTH

SF-1201 (RS-69)

VALVES WILL BE INSPECTED AND REPAIRED DURING THIS OUTAGE.

B B STEPHENSON, SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON COMPANY RR 1 MORRIS IL 60450

NNNN

8306130037 750602
PDR ADOCK 05000249
S PDR

COPY SENT TO:

FDR ✓
LDR ✓
NSIC
TIC