

MGMWSHT HSB

2-039868D080-012 03/21/74

SUSPECTED DUPLICATE 2-034698E080 1CS 1PMBNGZ CSP
3096542241 MGM TDBN CORDOVA IL 110 03-21 0547P EDT
ZIP 20545

Mailgram



50-254

JOHN F O'LEARY

DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545



REFERENCE QUAD CITIES NUCLEAR POWER STATION DOCKET NUMBER 50-254
DPR-29 APPENDIX A SECTION 1.0.A.2 AND 1.0.A.4 AND 3.7.A.1.A
6.6.B.1.A AT APPROXIMATELY 1500 HOURS ON MARCH 21 1974 DURING
ROUTINE QUARTERLY CALIBRATION CHECK OF UNIT ONE SUPPRESSION
CHAMBER LEVEL TRANSMITTER LT 1-1626 INSTRUMENT WAS FOUND TO
HAVE POOR RESPONSE CHARACTERISTICS SENSING LINE WERE BACK FLUSHED
AND INSTRUMENT WAS RECALIBRATED FOLLOWING CALIBRATION TORUS
LEVEL WAS FOUND TO BE READING MINUS 4 INCHES EXCEEDING TECHNICAL
SPECIFICATIONS 3.7.A.1.A STEPS WERE TAKEN TO IMMEDIATELY RESTORE
THE SUPPRESSION CHAMBER LEVEL TO WITHIN SPECIFICATIONS BY ADDING
WATER FROM THE CONTAMINATED CONDENSATE STORAGE TANK

N J KALIVIANAKIS

18138 EST

MGMWSHT HSB

8306130077 740329
PDR ADOCK 05000254
S PDR

50-254
2426
COPY SENT REGION