



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

D. L. LANAIR

NJK-76-132

April 15, 1976

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station
Docket No. 50-254, DPR-29, Unit 1
Appendix A, Sections 3.9.E.2, 6.6.B.2.b

Enclosed please find Reportable Occurrence Report No. 50-254/76-13 for
Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of
Technical Specification 6.6.B.2.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
Station Superintendent

NJK/lk

cc: G. A. Abrell

1-78

8306130165 760415
PDR ADOCK 05000254
S PDR

CENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME					LICENSE NUMBER								LICENSE TYPE					EVENT TYPE							
01		I	L	Q	A	D	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	0	0	3
7	8	9					14	15									25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE						REPORT DATE							
01	CON'T		L	0	5	0	-	0	2	5	4	0	3	1	7	7	6	0	4	1	6	7	6
7	8	57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

02	The 1/2 Diesel Generator was out-of-service too long for preventative	80
03	maintenance. At 1:00 pm on March 17, 1976 the 1/2 Diesel Generator	80
04	was taken out-of-service for preventative maintenance and did not get	80
05	returned to service until 2:35 pm. Normal off-site power and	80
06	both Unit Diesel Generators were available. (RO 50-254/76-13)	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
0	7	E	E	Z	Z	Z	Z	Z	Z	Z	Z	9	9	9	N		
7	8	9	10	11						12	13	14	15	16	17		

CAUSE DESCRIPTION

08	A communication problem between Operating Department and Maintenance	7 8 9	80
09	Department provided ineffective timing to return the Diesel Generator	7 8 9	80
10	to service within the allowable time set forth in Technical Specifications	7 8 9	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	9	7	NA		B	NA		
7	8	9	10	11	12	13	14	15	16	17

FORM OF ACTIVITY RELEASED

1 2

7 8

9

CONTENT OF RELEASE

Z

10

11

AMOUNT OF ACTIVITY

NA

44

45

LOCATION OF RELEASE

NA

80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	Z NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION
14	0	0	0	NA

OFFSITE CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	6	Z	NA

PUBLICITY

17 NA 80

ADDITIONAL FACTORS

18	(Cause Description continued) A precaution will be added
----	--

19 | to Station Procedures which should prevent reoccurrence.

NAME: Thomas J. Kelly PHONE: (309) 654-2241 Ext. 252