

Telegram

VEC233(1550)(2-16169 IE248)PD 09/05/73 1550

ICS IPMBNGZ CSP

3096542241 TDBN CORDOVA IL 112 09-05 0350P EST

PMS BOYCE GRIER, FONE

REGION 3 COMPLIANCE US ATOMIC ENERGY COMMISSION 799 ROOSEVELT
RD


GLEN ELLYN IL 60137

REFERENCE QUAD CITIES NUCLEAR POWER STATION DOCKET NUMBER 50-254
DPR29 APPENDIX A SECTION 1.0.8.2 3.1 6.6.B.1 WHILE PERFORMING
ROUTINE SURVEILLANCE CALIBRATION OF REACTOR PROTECTION SYSTEM
INSTRUMENTATION ON UNIT ONE ON SEPTEMBER 4 1973 A HIGH PRESSURE
SCRAM PRESSURE SWITCH WAS FOUND TO HAVE A SET POINT WHICH EXCEEDED THE
LIMITING CONDITION FOR OPERATION PFI-263-55A OF BARKSDALE MODEL
B2TA12SF PRESSURE SWITCH HAD DRIFTED TO A SET POINT OF 1062PSIG
WHICH IS CONTRARY TO THE 1060 PSIG MAXIMUM REQUIREMENT OF TABLE
5.1.1 OF THE SPECIFICATIONS ALL OTHER HIGH PRESSURE SCRAM SWITCHES

TRIPPED AT LESS THAN 1060 PSIG THUS THE NORMAL OPERATION OF
THE PROTECTION SYSTEM WAS NOT AFFECTED BY THIS ABNORMAL OCCURANCE
N KALIVIANAKIS

8306140280 730912
PDR ADOCK 05000254
S PDR

SEP 10 1973



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files

C. Incident Notification From: Commonwealth Edison Co. 50-254
(Licensee & Docket No. (or License No.))

Transmittal Date : September 10, 1973

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

U.S. ATOMIC ENERGY COMM.
DIVISION OF COMPLIANCE

1973 SEP 13 AM 11 46

RECEIVED