

SAFE POWER FOR MAINE

L Hollander
President
G. Garrett
Vice-President
Technological Advisor
A. Townley
Vice-President
Treasurer
Smith
Administrative Director

Public Information Office
12 Main Street
Camden, Maine 04843
(207) 236-3610

Executive Office
Stockton Springs, Maine 04981
(207) 567-3333, 3300, 3567

RFW -
Pls ask RII to
provide a response.
BOARD OF TRUSTEES
Robert O. Binnewies
Bradford B. Brown
John N. Cole
John Donovan
Buckminster Fuller
Lorin Hollander
Stanley Tupper
Neil Welliver

9 Sept 75

To: U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, D.C.

Gentlemen:

Please provide me with some details of the inoperable status of both diesel generators for 23 hours on 4 and 5 March 1975 at Dresden 3.

Also, what would be the most serious consequences of failure of the generators coupled to a loss of off-site power?

Are there any NRC restrictions on the operation of a reactor when all of the emergency generators are known to be inoperable or when a loss of off-site power is experienced?

Sincerely,

Pat Garrett
Pat Garrett

ECISPA

8306150160 751021
PDR ADOCK 03000249
PDR