



Telegram

VEE234(1751)(2-037548E049)PD 02/18/75 1751

1975 FEB 18 PM 4:51

ICS IPMBNGZ CSP

8159424449 TDBN MORRIS IL 74 02-18 0551P EST

PMS JAMES G KEPPLER, REGIONAL DIRECTOR, DIRECTORATE OF REGULATORY
OPERATIONS-REGION 3, US ATOMIC COMMISSION, WUX

799 ROOSEVELT RD

312-858-2660

GLEN ELLYN IL 61037

SUBJECT, DPR-25, DRESDEN NUCLEAR POWER STATION UNION 3.

THIS WILL CONFIRM A CONVERSATION WITH PHIL JOHNSON OF YOUR OFFICE AT
1530 HOURS THIS DATE CONCERNING FAILURE OF BERGEN PATTERSON PIPING
RESTRAINT NUMBER 19 ON THE UNIT 3 HPCI MAIN STEAM LINE IN THE
DRY-WELL DUE TO LOSS OF HYDRAULIC FLUID DURING OPERATION. THE
SNUBBER IS BEING REPLACED WITH A REBUILT SNUBBER. SEAL MATERIAL WAS
ETHYLENE-PROPYELENE.

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON CO RRI MORRIS IL 60450

FEB 21 1975

8306150244 750218
PDR ADDCK 05000249
PDR

(R5-69)

ATTEMPTS TO DELIVER:

W. H. H. H.