



Commonwealth Edison  
Quad-Cities Generating Station  
Post Office Box 216  
Cordova, Illinois 61242  
Telephone 309/654-2241

K-75-437

ccopy: Region III, Attention: Mr. C. Feierabend

August 31, 1975

Mr. Keppler, Regional Director  
Office of Inspection and Enforcement  
Region III  
U.S. Nuclear Regulatory Commission  
199 Roosevelt Road  
Deerfield, Illinois 60015

Reference: Quad-Cities Nuclear Power Station, Unit 2  
Docket No. 50-265, DPR-30  
Appendix A, Sections 1.0.A.4, 3.5.E.1, 6.6.B.1a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an  
Abnormal Occurrence as required by Technical Specification 6.6.B.1.a  
within 24 hours of the occurrence.

On August 30, 1975, while performing the monthly RCIC operability  
surveillance test, it was discovered that the RCIC would not reach  
rated conditions, but would trip at 3500 RPM. Approximately  
3000 RPM was needed. A failure in the overspeed mechanism is sus-  
pected. The RCIC system was declared inoperable and the required  
testing of the HPCI system was initiated.

This occurrence was discussed by telephone with Mr. Allen of your  
Office on August 30, 1975. Further information will be provided by  
Abnormal Occurrence Report AO 50-265/75-34 which will be submitted  
within 10 days of the date of this occurrence.

Sincerely yours,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

*J. Kalivianakis*  
J. Kalivianakis  
Station Superintendent

K/RAR/saa

Office of Nuclear Reactor Regulation  
G. A. Abrell