

DDD

DDDD

DD

WESTERN UNION INCOMING

*But 008*

USAEC HQS GTWN

50-249

TLXA037 WAG037(0917)(1-003934C160002)PD 06/09/73 091573 JUN 11 11 08 01

ICS IPMVEIA MVN

U.S. ATOMIC ENERGY COMM.  
WASHINGTON

01019 TDVE MORRIS IL 113 06-08 556P CDT

PMS MR A GIAMBUSSO

DEPUTY DIRECTOR FOR REACTION PROJECTS

DIRECTORY OF LICENSING

U S ATOMIC COMMISSION

WASHDC 20545

SUBJECT: DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3

VISUAL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT 1650 HOURS THIS DATE CONCERNING FAILURE OF HPCI STEAM SUPPLY VALVE 2301-3. ON 6-8-73 WHILE CONDUCTION VALVE OPERATABLE CHECK ON HPCI. VALVE 2301-3 FAILED TO OPEN 100%. WITH THIS VALVE IN A MID-POSITION IT WAS DECIDED TO DECLARE HPCI INOPERATABLE. THE SHIFT WAS INSTRUCTED TO BEGIN REQUIRED SURVILLANCE BY 1545 HOURS THE MAINTAINANCE CREW INVESTIGATED THIS PROBLEM. HAD TO MANUALLY OPEN THE VALVE. AT THAT TIME HPCI WAS DECLARED OPERATABLE. THE MAINTAINANCE CREW WILL CONTINUE TO CHECK VALVE TO DETERMINE THE CAUSE FOR ITS FAILURE. NECESSARY REPAIR WILL BE MADE AS SOON AS POSSIBLE.

W P WORDEN

SUPERINTENDENT

PRESIDENT DRESDEN POWER STATION



8306160146 740322  
PDR ADOCK 05000249  
S PDR

COPY SENT REGION *11*

3731



Telegram

1973 JUN -9 AM 9:23

VED036(0917)(1-003934C160)PD 06/09/73 0915

ICS IPMVEIA MVN

01018 TDVE MORRIS IL 113 06-08 556P CDT

PMS MR BOYST GRIER, DIRECTOR DIV OF COMPLIANCE

DIV 3 WX U S ATOMIC ENERGY COMMISSION

799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3

VISUAL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR OFFICE AT

1650 HOURS THIS DATE CONCERNING FAILURE OF HPCI STEAM

SUPPLY VALVE 2301-3. ON 6-8-73 WHILE CONDUCTION VALVE

OPERATABLE CHECK ON HPCI. VALVE 2301-3 FAILED TO OPEN 100%.

WITH THIS VALVE IN A MID-POSITION IT WAS DECIDED TO DECLARE

HPCI INOPERATABLE. THE SHIFT WAS INSTRUCTED TO BEGIN REQUIRED

SUVILLENCE BY 1545 HOURS THE MAINTAINANCE CREW INVESTIGATED

THIS PROBLEM. HAD TO MANUALLY OPEN THE VALVE. AT THAT TIME

HPCI WAS DECLARED OPERATABLE. THE MAINTAINANCE CREW WILL

CONTINUE TO CHECK VALVE TO DETERMINE THE CAUSE FOR ITS FAILURE.

NECESSARY REPAIR WILL BE MADE AS SOON AS POSSIBLE.

W P WORDEN

SUPERINTENDENT

PRESIDENT DRESDEN POWER STATION

TELEGRAMS (OTHER THAN MONEY ORDERS)

Is PRACICAL DELIVERY expected? (YES-AGENT, NO-ADDRESSEE)

4/11

NE

10

10

10

10

10

10

10

10

10

JUN 13 1973