

western union

Telegram

1973 APR 16 PM 6:18

VEB246(1916)(1-032340C106)PD 04/16/73 1914

ICS IPMVEIA MVN

01237 TDVE MORRIS IL 112 04-16 535P CST

PMS MR BOYCE GRIER, DIRECTOR DIVISION OF COMPLIANCE

REGION THREE US ATOMIC ENERGY COMMISSION

799 ROOSEVELT RD GLEN ELLYN IL 60137

SUBJECT DP4-25

DRESDEN NUCLEAR POWER STATION UNIT THREE.

THIS WILL CONFIRM A CONVERSATION WITH MR MAURA OF YOUR
OFFICE AT 1530 HOURS THIS DATE CONCERNING TWO SUSTAINED HIGH
REACTOR PRESSURE SWITCHES BEING OUT OF CALIBRATION. THESE PRESSURE
SWITCHES INITIATE ISOLATION CONDENSOR AFTER A FIFTEEN SECOND
TIME DELAY. ON 4-13-73 PS3-263-53B WAS FOUND TO TRIP AT
1075PSIG AND PS3-263-53D WAS FOUND TO TRIP AT 1073PSIG. TABLE
3.2.2 OF THE TECHNICAL SPECIFICATION STATES THE TRIP LEVEL
SETTING SHOULD BE LESS THAN OR EQUAL TO 1070PSIG.

8F-1201 (R5-68)

AFTER THE CALIBRATION SWITCH 53B TRIPPED AT 1052PSIG AND THE
SWITCH 53D AT 1056PSIG.

W P WORDEN SUPERINTENDANT

DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON CO

RR1

MORRIS ILLINOIS

8306160191 730419
PDR ADDCK 05000249
S

TELEGRAMS (OTHER THAN MONEY ORDERS,
IS CAL DELIVERY requested? (YES-AGENT, NO-ADDRESSEE SECTION
N.R.
Date 4/17 Time did 850A To P.G. By EB
To be or filed m
Attempts to deliver (Indicate DA or BY)