



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-422

Telecopy: Region III, Attention: Mr. C. Feierabend

August 18, 1975

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.5, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

On August 17, 1975 while bringing Unit Two back to power following a maintenance outage, the 6" to 4" reducer on the downstream side of low flow feedwater regulating valve, 2-643, severed due to vibration incurred while transferring from the low flow feedwater regulating valve to the main feedwater regulating valve.

The unit was manually scrammed and the reactor level was maintained with the RCIC system. Although contaminated water was introduced into the oil separator none was released to the environs.

This occurrence was discussed by telephone with Mr. Knop of your office on August 17, 1975. Further information will be provided by Abnormal Occurrence Report A0 50-265/75-31 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

NJK/lk

cc: Office of Nuclear Reactor Regulation
G. A. Abrell

8306160205 750827
PDR ADOCK 05000265
S PDR

AUG 20 1975