



Commonwealth Edison  
Quad-Cities Generating Station  
Post Office Box 218  
Cordova, Illinois 61242  
Telephone 309/654-2241

NJK-75-363

Telecopy: Region III, Attention: Mr. C. Feierabend

July 18, 1975

J. Keppler, Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2  
Docket No. 50-265, DPR-30  
Appendix A, Sections 1.0.A.2, 3.1.a, Table 3.1.1

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.


At 9:30 A.M. on July 18, 1975, while performing routine quarterly surveillance, pressure switch 2-1001-898, which trips on High Drywell Pressure, failed to operate at any pressure. Work request 2640-75 was initiated to investigate and correct the problem.

All three of the other drywell pressure sensors operated properly; therefore, had a High Drywell pressure occurred, the trip system would have performed its designed function.

This occurrence was discussed by telephone with Mr. Feierabend of your office on July 18, 1975. Further information will be provided by Abnormal Occurrence Report AO 50-265/75-23 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

  
N.J. Kalivianakis  
Station Superintendent

NJK/vb

cc: Director of the Office of Nuclear Reactor Regulation  
J.S. Abel

8306170172 750725  
PDR ADOCK 05000265  
S PDR

7/18/75  
3.53

K.S.