



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-493

TELECOPY: Region III, Attention: Mr. C. Feierabend

October 7, 1975



J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. NUCLEAR REGULATORY COMMISSION
799 Roosevelt Road
Glen Ellyn, IL 60137

REFERENCE: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.5, 6.6.B.1.a

Dear Mr. Keppler:


The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit 2 in the Cold Shutdown condition during a scheduled Core Maintenance Outage, an inspection revealed that a pipe crack had occurred on feedwater flush line 2-3206B-4"-C at the point where it taps into main feedwater line 2-3204B-18"-C. The resulting minor leakage to the steam tunnel has not affected reactor inventory, and repairs are being initiated.

This occurrence was discussed with Mr. Feierabend of your office on October 7, 1975. Further information will be provided by Abnormal Occurrence Report A0 50-265/75-37 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK/LG/dkp

cc: Office of Nuclear Reactor Regulation
G. A. Abrell

8306170255 751017
PDR ADOCK 05000265
S PDR