



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

Files

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files
RO Files

C. Incident Notification From: Consumers Power Co. Docket No. 50-255
(Licensee & Docket No. (or License No.))

Transmittal Date : April 24, 1974

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
RO Files

8306200301 740426
PDR ADOCK 05000255
S PDR

*Incident
50-255*



Telegram

VEB277(1320)(1-019900A106)PD 04/16/74 1316

TLX CONSPower JKN

ZCZC 003 JACKSON MICHIGAN 4-16-74

PMS MR ED JORDAN

USAEC

REGION III

799 ROOSEVELT ROAD

GLEN ELLYN, IL 60137

TELEGRAMS (UNITED STATES AND FOREIGN COUNTRIES)
IS PHYSICAL DELIVERY
AGENT SECTION
Vbr. & Name
date dtd 4-16
to be mailed or filed
attempts to deliver (Indicate DA or BY)
D.B. ADDRESSEE
312-858-2660
228P PTC By 97
mail

WHILE REVIEWING THE REFUELING SURVEILLANCE CALIBRATION SHEETS IT WAS NOTED THE PRESSURIZER PRESSURE SENSORS PT-0102 HAD DRIFTED DOWN -INDICATING 10N-. THIS CAUSED A MORE CONSERVATIVE SETTING ON PRESSURIZER HIGH PRESSURE TRIP PA-0102H BUT A LESS CONSERVATIVE SETTING ON SAFETY INJECTION SIGNAL PIC-0102LL. THE LARGEST SENSOR DRIFT WAS 20 PSI - TWO PERCENT. SYSTEM SETTINGS HAD BEEN ESTABLISHED ASSUMING

SF-1201 (RS-69)



Telegram

A FIVE PSI - .5 PERCENT DRIFT AS SPECIFIED BY THE VENDOR. THUS TWO CHANNELS C AND D WERE FOUND 15 PSI LOWER THAN REQUIRED TECH SPEC SETTINGS AS LISTED IN 3.16.1.2 AND CHANNEL A WAS 5 PSI LOW.

SINCE THESE PRESSURE TRANSMITTERS WERE SPECIALLY MODIFIED BY THE VENDOR TO WITHSTAND MHA CONDITIONS, VENDORS RECOMMENDATIONS ARE BEING SOUGHT.

R B DE WITT

CONSUMERS POWER COMPANY

PALISADES PLANT

ALL DBW

NNNN

APR 17 1974

SF-1201 (RS-69)