

MAR 19 10 03 AM '77

1000

THIS INCIDENT WAS CAUSED BY PREVIOUS INTERPRETATION OF  
LESS THAN OR EQUAL TO SETPOINTS AND IMPROPER SWITCH APPLICATION.  
THE ORIGINALLY SPECIFIED SWITCH HAD AN ADJUSTABLE RANGE OF 0-100 PSI.  
ASSUMING A 1 PER CENT REPEATABILITY OVER A ONE YEAR PERIOD THIS  
SWITCH COULD RESULT IN A 1 PSI DRIFT.

CORRECTIVE ACTION IS TO SET THE EXISTING SWITCH TO THE  
REQUIRED SETPOINTS, THEN ORDER THE IMPROVED UNITED ELECTRIC J-302-553  
PRESSURE SWITCH WITH A 0-20 PSI ADJUSTABLE RANGE.

AN532855/JGLE

WDEWITT/JCLEWIS


PALISADES NUCLEAR PLANT

COVERT MICHIGAN

MAR 21 1974

ALL

US AEC ARGN



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TELEPHONE  
(312) 858-2660

*File*

A. RO Inspection Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:

RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:

RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

B. RO Inquiry Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:

RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:

RO Chief, FS&EB  
RO:HQ  
DR Central Files  
RO Files

C. Incident Notification From: Consumers Power Co. Docket No. 50-255  
(Licensee & Docket No. (or License No.))

Transmittal Date : March 27, 1974

Distribution:

RO Chief, FS&EB  
RO:HQ (4)  
Licensing (4)  
DR Central Files  
RO Files

Distribution:

RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files