

# LICENSEE EVENT REPORT

Palisades

CONTROL BLOCK:                  

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE						EVENT TYPE	
M I P A L 1														0 0 - 0 0 0 0 0 0 - 0 0														4 1 1 1 1						0 1	
7 8 9 14														15 25														26 30						31 32	

  

CONT				REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE						REPORT DATE									
0 1				*		*		T		L		0 5 0 - 0 2 5 5										0 1 1 7 7 7						0 2 0 2 7 7					
7 8 9 57 58				59		60		61 68 69										74						75 80									

## EVENT DESCRIPTION

02	Following a feed-water pump trip, the operator attempted to avert a reactor trip by	80
03	manually running in the control rods, but did not switch mode selector from auto to	80
04	manual resulting in rod No 38 being driven in 13.6 inches below the group before	80
05	realizing the error. The other operator immediately tripped the plant.	80
06	(ER-77-08)	80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
R B		A		C O N R O D				N		C 4 9 0				Y	
7 8 9 10		11		12 17				43		44 47				48	

## CAUSE DESCRIPTION

08	Personnel Error	80
09		80
10		80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
C		0 3 5		NA		a		NA					
7 8 9		10 12		13		44 45		46 80					

  

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
Z		Z		NA				NA					
7 8 9		10 11		44				45 80					

## PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION					
0 0 0		Z		NA					
7 8 9 11		12		13 80					

## PERSONNEL INJURIES

NUMBER		DESCRIPTION					
0 0 0		NA					
7 8 9 11		12 80					

## PROBABLE CONSEQUENCES

15	NA	80
----	----	----

## LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION					
Z		NA					
7 8 9 10		80					

## PUBLICITY

17	NA	80
----	----	----

## ADDITIONAL FACTORS

18	NA	80
----	----	----

19	NA	80
----	----	----