



Commonwealth Edison
 Quad-Cities Generating Station
 Post Office Box 216
 Cordova, Illinois 61242
 Telephone 309/654-2241



NJK-74-445

Telecopy: Region III, Attention: Mr. C. Feierabend

December 31, 1974

J. Keppler, Regional Director
 Directorate of Regulatory Operations
 Region III
 U. S. Atomic Energy Commission
 799 Roosevelt Road
 Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
 Docket No. 50-265, DPR-30
 Appendix A, Sections 1.0.A.2, 4.7.A.2.1.2.B, 6.6.B.1.A

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit 2 in the cold shutdown condition for the current refueling outage, main steam isolation valves were leak rate tested.) The following results were determined from the tests:

Within leak rate limitations: 2-203-1C, 2-203-1D, 2-203-2D
 exceeded leak rate limitations: 2-203-1A, 2-203-1B, 2-203-2C

Due to water leaking through two of the leaking inboard MSIV'S, an accurate numerical leak rate value could not be determined for 2-203-2A and 2-203-2B.

In accordance with our previous reporting agreement of April 4, 1974, this notification also fulfills the Ten Day Reporting Requirement of Technical Specification 6.6.B.1.B. Details of repairs necessary to correct these deficiencies will be reported at a later date when the work is complete.

This occurrence was discussed by telephone with Mr. Feierabend of your office on December 30, 1974. Further information will be provided by Abnormal Occurrence Report AO 50-265/74-32.

Very truly yours,

COMMONWEALTH EDISON COMPANY
 QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
 N. J. Kalivianakis
 Station Superintendent

NJK/LDR/vmm

cc: Directorate of Licensing
 J. S. Abel

8306290366 750518
 PDR ADDCK 05000265
 S PDR