

from Davis - Besse
docs

9/28/77

Review of ^{Invest at} ~~accident~~ on 9/28/77

Name ^{6PU} ~~3/23/82~~ EXHIBIT 488 FOR IDENT
H. A. RUDOLPH

Representing

Garry Haley
Tom H. Winkler
E. Knight
M. Newman
Don Lee
C. Lindvall
~~Thick~~
~~Michael~~
M. McArthur
Sid Hill
D. Dibert
TL Hatcher
JJ Kelly
Tom Reddaway
Bob Benis
Fred Miller
Ray Lund
B. D. Boyer
C. D. Miller
T. Mueser
J. Miller
Paul J. Jant

TECO - D-B
local 245
TECO
TECO
test program
Test Program
Terry Toss
TECO
B. W
TECO
TECO
NRC
B+W
Bechtel Startup
TECO - Pres. ENGR.
" " "
" " "
TECO D-B
Bechtel GPDE
TECO
TECO
B+W

King
note

9/28/77 AT D-B MTG on 9/27/77 ~~Emergency Incident~~
(NAC in attendance) FRM Ray Sund:

2 No indication on position of S.U. F.W. Valve

1 mi 15 sec after RPS trip had full SFAS trip
= Reddaway - which records on scheme elect a missing relay
1-1 RCP turned off 2-2 ~~(S)~~ RCP off 40 sec later per
computer (but operator tripped at same time)
request = 2 S.G. went dry - Later to verify, 7 dies #1 S.G. by ?
P.R.Z.R. went solid (F. Faist) T. Murray SAID NO &
there were no press spikes
P.R.Z.R. compensated over Recorder was off scale at high end

Was manually blocked at P. low S.G. pressure so #2 AFD did not
transfer to #1 S.G. so allowed operator to go on manual AFD
speed control & established RPM to 3600 to feed #2 S.G. & restore press but
Tours still decreased rapidly so ~~the~~ manually decreased speed as thought
was quick work S.G. #2 - left @ low speed for about 1 minute &
then put on auto level control for #2 AFD.

RC 11 position alarm on comp? op could not locate it.
SE BSW - write up a pre & sec side happenings
Evaluate S.G. Boils dry
" excursion effect on equipment
Aux F.P. problem
FCR - replace governor
2 SE suggest BOP around the Gov Valve linkage

gov had a post opened up
wrote co 3 individual LER DBR
? get reserts out of RACCA



