



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 218
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-74-281

Telecopy: Region III, Attention: Mr. C. Feierabend

September 17, 1974

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60127

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.5, and 6.6.B.1.a.

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of and Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

Following discovery of abnormalities associated with welds on the recirc pump discharge valve bypass line at Dresden Nuclear Power Station, a total of 22 similar welds were tested on the recirc loops at Quad-Cities Unit 2. One weld abnormality was discovered at the upstream connection of the "3" recirc pump discharge valve bypass line (2-0203B-4'A) to the "B" recirc pump discharge line (2-0201B-28'A). The abnormality is located between the recirc pump and the pump discharge valve. Repairs to the weld involved are in progress.

This occurrence was discussed by telephone with Mr. C. Feierabend of your office on September 16, 1974. Further information will be provided by Abnormal Occurrence Report AO 50-265/74-25 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

NJK:CWS/zr

cc: Directorate of Licensing
J. S. Abel



50-265
requiring

9701 *III*

COPY SENT REGION

8307130239 740926
PDR ADDCK 05000265
S PDR