



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 809/854-2241

NJK-74-328

Telecopy: Region III, Attention: Mr. C. Feierabend

October 12, 1974

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 1
Bucket No. 50-254, DPR-29
Appendix A, Sections 1.0.A.5, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

While inspecting Unit 1 Drywell during startup on October 12, 1974, a pinhole leak was discovered at an elbow socket weld in 3/4 inch carbon steel line 1-261-3C. The unit was shutdown. The weld was dye penetrant tested, ground out, rewelded, and again dye penetrant tested.

This occurrence was discussed by telephone with Mr. E. Jordan of your office on October 12, 1974. Further information will be provided by Abnormal Occurrence Report AO 50-254/74-33 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

8307130270 741022
PDR ADOCK 05000254
S PDR

NJK/CWS/lk

cc: Directorate of Licensing
J. S. Abel

OCT 15 1974

gks