



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Corroia, Illinois 61242
Telephone 309/654-2241

NJK-74-327

TELECOPY: Region III, Attention: Mr. C. Feierabend

October 11, 1974

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. ATOMIC ENERGY COMMISSION
799 Roosevelt Road
Glen Ellyn, Illinois 60137

REFERENCE: QUAD-CITIES NUCLEAR POWER STATION, Unit 1
Docket No. 50-254, DPR-29
Appendix A, Sections 1.0.A.2, 3.2.B., Table 3.2.2,
6.6.B.1.a.

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a. within 24 hours of the occurrence.

On October 10, 1974 while performing routine surveillance calibration testing of LIS-1-263-72C, it was discovered that switch number one would not trip regardless of test pressure applied. The mercury switch was realigned and recalibrated. The switch was retested on October 11, 1974 and found to be satisfactory. A routine functional test is planned next month for this switch.

This occurrence was discussed by telephone with Mr. E. Jordan of your office on October 11, 1974. Further information will be provided by Abnormal Occurrence Report AO 50-254/74-32 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

NJK:CWS/dkp

8307130279 741018
PDR ADOCK 05000254
S PDR

cc: Directorate of Licensing
J. S. Abel

OCT 11 1974

348p