

WESTERN UNION INCOMING

BETH  
008

1973 JUN 21 PM 4 30

50-261

U.S. ATOMIC ENERGY COMM.  
TWX UNIT

WU WSH

+

USAEC HQS GTWN

TLXA081 WAG144(1426)(2-234151E172)PD 06/21/73 1426

ICS IPMMIZZ CSP

8033321351 TDMT HARTSVILLE SC 118 06-21 0226P EST

PMS JOHN S OLEARY

DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION

WASHINGTON DC 20545

IN ACCORDANCE WITH 6.6.2 OF THE TECHNICAL SPECIFICATION, THE FOLLOWING ABNORMAL OCCURENCE IS REPORTED: ON JUNE 20, 1973, AT 1454 HOURS WHILE PERFORMING A TEST OF THE TURBINE REDUNDANT OVERSPEED TRIP SYSTEM (TROTS) A TURBINE TRIP OCCURRED. AN IMMEDIATE REACTOR TRIP DID NOT OCCUR DUE TO A TURBINE STOP VALVE LIMIT SWITCH MALFUNCTION. A REACTOR TRIP DID OCCUR DUE TO HIGH PRESSURIZER PRESSURE.

THE TURBINE STOP VALVE LIMIT SWITCH WAS ADJUSTED AND SATISFACTORILY OPERATED PRIOR TO INITATING POWER OPERATION.

THE INCIDENT HAS BEEN REVIEWED BY THE PLANT NUCLEAR SAFETY COMMITTEE

AND SAFE REACTOR OPERATION IS ASSURED.

THIS WAS REPORTED TO MR SIEDLE OF DRO BY TELEPHONE ON JUNE 21 1973

B J FURR PLANT MGR CAROLINA POWER AND LIGHT CO H B ROBINSON  
SEG PLANT HARTSVILLE SC PO BOX 790 29550

+

USAEC HQS GTWN

431P EDT

WU WSH

8307200435 730628  
PDR ADOCK 05000261  
S PDR

Handwritten  
50261

4038

COPY SENT REGION