

Telegram

947A EDT OCT 20 72 AA040 AAA030(0836) (1-0041820294) PD
10/20/72 0834

ICS IFMCMAB CLB

ZCZC 010 B VN PDF 6 EXTRA TDCM HARTSVILLE SOCAR 20 907A EDT
PMS JOHN DAVIS, FONE

DIRECTOR OF REGION 2 AEC DIVN OF COMPLIANCE 230 PEACHTREE ST
ATLA

THURSDAY 10/19/72 THE HORON INJECTION TANK AND B BORIC ACID
TANK WERE FOUND TO HAVE A LOW CONCENTRATION OF BORIC ACID.
STEPS WERE INITIATED TO RETURN THE TANKS TO THEIR NORMAL
CONCENTRATION. ALL TANKS ARE NOW WITHIN SPECIFICATIONS. THIS
IS REPORTED IN ACCORDANCE WITH SECTION 6.6.1.A OF THE TECHNICAL
SPECIFICATIONS

BENNY J FURR PLANT MANAGER H B ROBINSON
LANT CAROLINA
POWER AND LIGHT

CF-1201 (RS-65)

11

Telegram

10/19/72 6.6.1.A

AA030/2

8307250342 730412
PDR ADOCK 05000261
P PDR