

# Carolina Power & Light Company

Raleigh, North Carolina 27602

January 20, 1972



50-261

Dr. Peter A. Morris  
Division of Reactor Licensing  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

H. B. ROBINSON STEAM ELECTRIC PLANT  
LICENSE DPR-23

"2A" EMERGENCY DIESEL TRIP TO HIGH CRANKCASE PRESSURE

Dear Dr. Morris:

In accordance with Paragraph 6.6.1.c Technical Specifications,  
the following abnormal occurrence is reported:

On January 17, 1972, "2A" emergency diesel tripped  
immediately after a remote manual start was initiated due  
to high crankcase pressure. The alarm was reset, the  
diesel restarted and successfully operated for 30 minutes.

This occurrence was reported to AEC Division of Compliance  
by telephone and telegraph on January 17, 1972.

Yours very truly,

E. E. Utley  
Manager

Generation & System Operations

NBB:dds

cc: Mr. C. D. Barham  
Mr. N. B. Bessac  
Mr. G. P. Beatty

2/3  
d/K  
RS  
g/K  
JN

8307250783 720120  
PDR ADDCK 05000261  
S PDR

434  
COPY SENT REGION