



western union

Telegram

432P EST JAN 4 72 AA360 KB242

K CMA271 CH PD 2 EXTRA HARTSVILLE SOCAR 4 314P EST
JOHN DAVIS

DIRECTOR REGION NO 2 A E C DIV A COMPLAINT 230 PEACHTREE
ST ATLA *230 Ptra*
ON JAN 3 2B EMERGENCY DIESEL FAILED TO START FROM A SIGNAL
INITIATED FROM THE R T G B THIS REPORT IS MADE IN ACCORDANCE
WITH TECHNICAL SPECIFICATIONS 6.6.1 WITH TECHNICAL MC REPORT
TO FOLLOW

G P BEATTIE JR S P AND L HARTSVILLE SOCAR

3 2B R T G B 6.6.1 MC
(428).

8307250804 720106
PDR ADDCK 05000261
S PDR

577 3664

DISC LW 9208

IBNFL

PM
DA WL 515P