

# LICENSEE EVENT REPORT

CONTROL BLOCK:                    

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE			
01	M	I	P	A	L	1				0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1	
7	8	9				14				15											25	26				30	31	32

  

REPORT TYPE			REPORT SOURCE			DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CON'T			T	L	0	5	0	-	0	2	5	5	0	5	1	0	7	6	0	5	2	5	7	6	
7	8		57	58	59	60	61					68	69							74	75					80

## EVENT DESCRIPTION

02	Diesel Generator 1-1 was made inoperable for preventative maintenance while one of																									80
03	two HPSI pumps, associated with the operable diesel, was inoperable. Corrective																									80
04	action taken has involved both a review of this event by the Supervisor involved																									80
05	and review of possible procedure changes which would utilize a checklist for remov-																									80
06	ing safety-related equipment from service. We expect procedure changes (ER-76-14)																									80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	E	E	A	G	E	N	E	R	A	Z	Z	9	9	9	Y		
7	8	9	10	11	12				17	43	44			47	48		

## CAUSE DESCRIPTION

08	The cause of this event was an oversight by the operations staff.																									80
09																										80
10																										80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
11	C	0	2	5	NA					a	NA				
7	8	9	10	12	13					44	45	46			80

  

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE				
12	Z	Z	NA					NA					
7	8	9	10	11					44	45			80

## PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION					
13	0	0	0	Z	NA				
7	8	9	11	12	13				80

## PERSONNEL INJURIES

NUMBER		DESCRIPTION						
14	0	0	0	NA				
7	8	9	11	12				80

## PROBABLE CONSEQUENCES

15	None, a redundant pump was available.																									80
----	---------------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

## LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION				
16	Z	NA				
7	8	9	10			80

## PUBLICITY

17	NA																									80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

## ADDITIONAL FACTORS

18	(Description contd) to be completed by July 1, 1976.																									80
19	<div style="display: flex; justify-content: space-between;"> <span>8308150203 760525</span> <span>PDR</span> </div> <div style="display: flex; justify-content: space-between;"> <span>PDR ADOCK 05000255</span> <span>PDR</span> </div> <div style="display: flex; justify-content: space-between;"> <span>S</span> <span>PDR</span> </div>																									80



Consumers  
Power  
Company

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

May 25, 1976



Mr James G. Keppler  
Office of Inspection Enforcement  
Region III  
US Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

DOCKET 50-255, LICENSE DPR-20 -  
PALISADES PLANT ER-76-12 -  
DIESEL GENERATOR & HPSI PUMP OUT OF SERVICE

Attached is a reportable occurrence which relates to the Palisades Plant. This occurrence has been classified as operation when an operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications.

Please note that this report is being submitted one day late per my telephone conversation with Ken Baker.

*David A. Bixel*

David A. Bixel  
Assistant Nuclear Licensing Administrator

COPY SENT REGION III

5812

JUN 4 1976