



Telegram

VEA245(1747)(1-036809C308)PD 11/04/74 1742

TLX CONSPower JKN

ZCZC 007 DLY JACKSON MICHIGAN 11-4-74

PMS US ATOMIC ENERGY COMMISSION
REGION III

799 ROOSEVELT ROAD

GLEN ELLYN, IL 60137

ATT: RON COOK

1974 NOV -4 PM 4:53
TELEPHONE NBR. 312-858-2660

TELEPHONED TO RC BY 71

DATE DLD 11/5/74 TIME 920P

ATTEMPTS TO DELIVER. mail

THIS IS A FOLLOW-UP ON TELEPHONE CONVERSATION WITH R J COOK TODAY CONCERNING TWO PALISADES INCIDENTS WHICH WE HAVE CLASSIFIED AS AB-NORMAL OCCURRENCES.

8308220462 741113
PDR ADOCK 05000255
S PDR

1. AO 74-25 LEAK IN T-90 PRIMARY MAKEUP TANK.

50-255 inquiry

THIS TANK HAS AN INTERNAL BLADDER HELD BY A PLATE WITH BOLTS PRO-

SF-1201 (R5-69)



Telegram

1974 NOV -4 PM 4:53


TRUDING THRU TANK WALL AT ABOUT 50 PERCENT DEVIATION. WHILE FILL-ING THE TANK WITH CLEAN WASTE EVAPORATOR DISTILLATE SLIGHT WEEPAGE WAS NOTED AROUND BOLTS ON EXTERIOR OF TANK. TANK WAS IMMEDIATELY PUMPED BACK DOWN FROM 52 PERCENT TO 49 PERCENT AND LEAK STOPPED. ESTIMATE MAXIMUM OF FIVE-GALLON LEAK TO SAND WITH 0.48 MILLICURIE TRITIUM AND .02 MILLICURIE NI 63.

THIS TANK BLADDER HAS LEAKED PREVIOUSLY AND REPAIRED. RESOLUTION OF PROBLEM UNKNOWN AT THIS TIME AND TANK WILL BE KEPT BELOW 49 PERCENT.

2. AO 74-26 DIESEL 1-1 LUBE OIL FAILURE.

DIESEL STARTED FOR MONTHLY TEST AND TRIPPED BACK OFF WITHIN SECONDS

SF-1201 (R5-69)


western union

Telegram

1974 NOV -4 PM 4: 53

DUE TO LACK OF PROPER OIL PRESSURE. IMMEDIATE INVESTIGATION INDICATES PROBLEM IS REAL AND OIL PUMP HAS FAILED.

DIESEL 1-2 HAS BEEN DEMONSTRATED OPERABLE AND NO ESS EQUIPMENT IN-OPERABLE PER TECH SPEC 3.7.2.1.

R B DE WITT/J G LEWIS
PALISADES PLANT
CONSUMERS POWER COMPANY
COVERT, MI

ALL HO

CC- R L HANETER


western union

Telegram

1974 NOV -4 PM 4: 53

R B SEWELL

NNNN

7 1974