



Telegram

VEB342(1500)(1-026246A192)PD 07/11/74 1458

ILX CONSPower JKN

ZCZC 009 JACKSON MICH 7/11/74

PMS US REC - ATT: RON COOK

799 ROOSEVELT

GLER ELLYN, IL 6-0137

TELEGRAM (OTHER THAN  
IN ORIGINAL MESSAGE CONTAINED  
LOCAL SECTION  
7-11 425y AC 114  
Mail  
LN 7/11 4102

THIS IS TO INFORM YOU OF A CONDITION AT PALISADES WHICH WE ARE  
TENTATIVELY CONSIDERING ABNORMAL OCCURRENCE 74-14 PENDING FURTHER  
INVESTIGATION.

IN REVIEW OF A QUARTERLY TECH SPEC TEST THIS WEEK, IT WAS NOTED  
THAT RPS1 PUMP P-66A SHUTOFF DISCHARGE PRESSURE WAS SUFFICIENTLY  
BELOW RATED TO RAISE THE QUESTION OF POSSIBLE PUMP DEGRADATION.

REPEAT TEST WILL BE RUN IN THE NEAR FUTURE TO ELIMINATE OTHER

CAUSES OF LOW-PRESSURE INDICATION. IF THE TEST PROVES DEGRADATION,  
IT WILL BE DISASSEMBLED AND REPAIRED PRIOR TO PLANT START-UP AND A  
FOLLOW-UP REPORT WILL BE ISSUED.

J G LEWIS/R B DE WITT  
CONSUMERS POWER COMPANY

CBW

8308230133 740412  
PDR ADOCK 05000255  
S PDR

COPY SENT TO: PDR  
LPDR  
NSIC  
TIC

CC: R B SEWELL

NNNN

JUL 15 1974