



Telegram

607P EDT SEP 10 73 AA194 AAD303(1703)(2-083562E253)PD

09/10/73 1703

ICS IPMBNGZ CSP

2057298316 TDBN ATHENS AL 79 09-10 0503P EST

FMS US ATOMIC ENERGY COMMISSION, WUX

DIRECTORATE OF REGULATORY OPERATIONS 230 PEACH TREE ST

ATLANTA GA 30303

SUBJECT BFAO 7311T

ON SEPTEMBER 10 1973 DURING INITIAL START UP TESTING AT 150
PSIG HPCI FAILED TO ACHIEVE RATED SPEED DURING AUTOMATIC QUICK
START IMMEDIATELY PRIOR TO THIS HPCI DID REACH RATED SPEED AND
REQUIRED FLOW DURING A MANUAL TEST AFTER REPLACING THE MAIN
CONTROL ROOM FLOW CONTROLLER AND CHECKING THE GOVERNOR RAMP
CONTROLL CIRCUITRY HPCI AGAIN FAILED TO REACH RATED CONDITIONS IN
THE AUTOMATIC MODE REACTOR PRESSURE WAS REDUCED BELOW 122 PSIG
TO ACCOMMODATE FURTHER STUDY

8F-1201 (RS-69)

Handwritten: 526-579

H J GREEN BROWNS FERRY NUCLEAR PLANT

Handwritten: 50259/260/276

8308290351 730920
PDR ADOCK 05000259
S PDR

8F-1201 (RS-69)