

*File*

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

October 25, 1974

Mr. Donald F. Knuth, Director  
Directorate of Regulatory Operations  
U.S. Atomic Energy Commission  
Washington, DC 20545

Dear Mr. Knuth:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENCY INVOLVING RUST ON  
INSIDE SURFACE OF REACTOR PRESSURE VESSEL

Initial report of the subject deficiency was made verbally to  
W. B. Swan, AEC-DRO Region II Inspector, on September 26, 1974.  
In compliance with paragraph 50.55(e) of 10 CFR Part 50, this  
is submitted as an interim report. TVA and Westinghouse are  
studying methods for correcting the subject deficiency. A  
report will be submitted upon completion of the studies.

Very truly yours,

*J. E. Gilleland*

J. E. Gilleland  
Assistant to the Manager of Power

. CC: Mr. Norman C. Moseley, Director  
Directorate of Regulatory Operations  
U.S. Atomic Energy Commission  
Region II - Suite 818  
230 Peachtree Street, NW.  
Atlanta, Georgia 30303

8308300017 741025  
PDR ADOCK 05000259  
S PDR