


MGMATLT HSR

2-013452E264 09/21/74

ICS IPMBNGZ CSP

2057298316 MGM TDBN ATHENS AL 101 09-21 0114P EDT

ZIP 30303



western union

Mailgram



U.S. ATOMIC ENERGY COMMISSION, ATTN REGION 2, DIRECTORATE OF REGULATORY
OPERATIONS
230 PEACH TREE ST NORTHWEST
ATLANTA GA 30303

BFA0-50-259/7448T AT 130PM SEPTEMBER 20, 1974 WHILE IN THE SHUTDOWN
COOLING MODE AT APPROXIMATELY 125 DEGREES F. UNIT 1 RHR PUMPS B
AND D EXPERIENCED FAILURE OF 1/2 INCH PIPE NIPPLES SUPPLYING PUMP
SEAL WATER REPLACEMENT NIPPLES ON BOTH PUMPS SUBSEQUENTLY FAILED
AND IT WAS NECESSARY TO USE NIPPLES OF A HEAVIER SCHEDULED PIPE.
PUMPS B AND D ARE PRESENTLY OPERATING SATISFACTORIALLY WHILE INVESTIGATION
ON AS TO CAUSE AND PERMANENT CORRECTIVE ACTION CONTINUES. RHR PUMPS
A AND C WERE OUT OF SERVICE FOR SCHEDULED MAINTENANCE AT THE TIME
H J GREEN, BROWNS FERRY NUCLEAR PLANT

13:14 EDT

MGMATLT HSB

PL. NY 11 12 23

SNOW - 11 11 11

COPY SENT TO: PDR ☒
LPDR ☒
NSIC ☐
TIC ☐

8308300161 740930
PDR ADOCK 05000259
S PDR